NEAR EAST UNIVERSITY



Faculty of Engineering

Department of Mechanical Engineering

DESIGN OF FOUNDRY FOR CASTING OF COVERINGS FOR TELECOMMUNICATIONSYSTEM

Graduation Project ME 400

Studentx

Nabil EI-SABEH (99~in3~'~)

Supervisor

Metin BiLiN

Lefkoşa - 2000





Preface

In the year 1982, the United Nations wanted to develop the communication system in Cyprus. So, they asked the governments of each of the two part of Cyprus to make a number of coverings *(062cm Manhole Covers)* that support the telephone cables from natural factors.

A foundry in Haspolat in Lefkosia suburbs was given that project; and after one year, around 2000 units was submitted. As n"fourth year mechanical engineering student at our great NEAR EAST UNIVERSITY, I toÔk the same project and I was lucky because Mr. Metin Bilin the engineer who designed the project in 1982 was my supervisor for the this project.

Abstruct _ (j)vvdivck-~- sv;; anomfeltured Muterial Introduction !

Dedicated to my family and to all my teachers, and sure for Mr. TAYSEER ALSHANABLI and MRS. FiLiZ ALSHANABLI

Who have brought a new level of love, patience, and understanding into our lives.

References:

Metals handbook by American society for metals Material and processes in manufacturing forE.PAUL DE.GARMO Note of manufacturing in the NEAR EAST UNNERSITY by MR. METIN BILIN

Ш

CH.1 THE FOUNDRY

1.1 Introduction		4
The product'		4
	—	5
1.2.1 A.rea	_	5
1.2.2 The Equipment:	_	5
1.2.3 Labor \sim		5
1.2.4 material''		6
1.2.5 Schedule ~		6
1.5 Sumniary;_	~	7
CH 2 THE PATTERN		8
2.1 introduction		8
2.2 Materials for pafterils / / ~ 2.2.1 Type of patterns /		8 9
2.3 Sek ction ofpaftetutype		9
2.4 Allowance		10
2.5 Conclusion		10
CH.3 THE CASTINGPROCESS		11
3.1 Introduction		11
3.2 Saud nwlding		11
3.2.1 Types of molds		11
3.2.3 Advantages of greellsaud molds		12
3.2.4 Disadvantages of green s~11d molds		12
3.2.5 Conditioning of molding sands, 3.2.5.1 The importance of sand treating		12 13
3.2.6 Allowance for metal shrinkage		13
3.2.7 Risers		13
3.3 Cleaning, the castings		14
3.3.1 Removal of gates and risers:		14
3.4 Saud cores and core making		14
3.4.1 Core requirement:		15
3.4.2 Core boxes.		15
3.4.3 Core mixture.		15

Δ

15
16
16
17
18
18
18
18
19
19
19
21
22
22
22
22
22
23 24
24
25
25
25
26 27 27
27
27
28
28
29
29
29
29

	5.2.2 Percentage amount of the part	30
	5.2.3The cost of one unit	30
	5.3 Summary	31
	Appendix 1: the cupola	32
	Appendix 2: size of cupolas	33
	Appendix 3: cross section of cupola bottom door	34
	Appendix 4: typical thickness of cupola lining	35
	Appendix 5: advantuges and disadvantages of cupola melting in a smallfoundry	36
	Appendix 6: temperature distribution in the cupola	37
	Appendi» 7: effect of blast air temperature on tapping temperature of iron	38
	Appendix 8: effect of blast air temperature on melting rate:	39
	Appendix 9: effect of blast air temperature on coke charge requirement.	40
	Appendix 10: comparison of characteristics of pattern materials	41
	Appendix 11: effect of itwisture contents in wood.	42
	Appendix 12: life ofpatteru	43
	Appendix 13 : pattem, of the coverpart	44
	Appendix 14: pattem of the chamber part	45
	Appendix 15: the core box	46
	Appendix 16: thefoundry outlook view	47
	Appendix 17: the shank typeladle	48
	Appendix 18: t/1e riser design	49
	Appendix 19: the mold preparing steps	51
	Appendix 20: theflask	52
	Appendix 21: the sand separator	53
2	Appendix 22: the Muller	54
	Appendix 23:A look at the mold	55
	1	

CH.1 THE·FOUNDRY

1.lintroduction

When to product something, it is very important to make the proper plan for the process, the proper selection for the way of production, the proper cost analysis and of course the proper production schedule.

The product.

Name: 062-cm manhole covers

Number of unit: 2000

Time for production: 1

Properties of the product:

l. Two parts :a *cover* and a *chamber*

2. M.aterial:gray cast iron

3. Weight:

a. 80 kg for the cover

b. 120 kg for the chamber

4. Manufacturing process: Casting

1.2 The foundry:

The main important parts of the foundry are:

- 1. the area
- ~2. the equipment
- 3. the labor
- 4. Raw material

1.2;1 Area

Since we are going to work on a schedule and there is a dead line for finishing all the parts, the area should be sufficient to be able to finish the parts on time. The foundry area is 360 m squa((i

1.2.2 The Equipment:

- a- A sand separator and binder.
- b- A Muller.
- c- A cupola.
- d- A crane. (3 ton capacity)
- e- 65 flask.
- f., 2 shank type ladle.(see appendix 17)
- g- Automatic squeezing machine. (2)

1.2.3 Labor

We need 6 labors. (4 for mold making, 1 for core making, and 1 furnace keeper).

1.2.4 material

- l.. 5 tons of sand
- 2. raw cast iron ((5% of 230kg)%2000piece=23 tons; take 25 tons)
- Scraps ((95% of 230 kg)%2000piece=437tons; take 440 tons); engine parts, car bodies, etc.
- 4. flasks (65 (cope and drag) made of iron sheet metal)
- 5. Coke we need 1 kg (coke) for each 7kg (charging), where charging is about /A40+25=465 tons, so we need 465/7=66.5 tons
- 6. limestone: 35% of coke; we need 0.35% 66.5 tons =23.5 tons

1.2.5 Schedule

Week	Mon.	Tue.	Wed.	Thu.	Fri.	Sat.	Sun.
S							
1 st	Casting	Cleanirıg	Mold	Preparing	Casting	Cleanin	holiday
	process	and mold	ınaking	the molds	process	g and	
		making		and cleaning		mold	
				the.cupola		making	
2 nd.	Preparing	Casting	cleaning	Möld	Preparing	holiday	holiday
	the molds	process		making	the molds		
	and				and		
	cleaning				cleaning		
	the				the		
	cupola				cupola		

It is seen that there will be casting three times every 14 days.

in order to be able to reach the dead line for work submission, 30 sets should be cast every casting day, which mean that 90 sets are to be cast every 14 days.

So we treed 44.44 week to complete our 2000 units, in other words 311 day, so we are 54 days before our dead line, which represents a factor of safety if some production problems happen.

1.3 Summary

Since all of these steps are properly found, one can probably get satisfactory results.

CH 2 THE PATTERN

2.1 introduction

Casting processes can be divided into two basic categories; those for which a new mold must be created for each casting (the expandable mold processes) and those that use a permanent reusable mold. Almost all of the expandable- mold processes begin with permanent, reusable pattern a duplicate of the part to be cast modified to reflect the casting process and the material beirg cast.

in the pattern making we should take care of the shrinkage that occurs while,~Ôlidification of the pattern.

The pattern also should have very dimensional accurate in order to have betler production results. Also the type of material of the pattern depend on the number of the casting being cast. For example if the number of casting is no more than 20 or 50 parts it is better to use a wood pattern since it is less expensive and the properties of the pattern .won't get lose before the end of the castings, but in the case of about 1000 pieces or more a metal pattern should be used because the dimensions won't get lose easily.

2.2 Materials for patterns

The materials of which pattern are usually made differ greatly in their characteristic and therefore in th~ applications to which they are suited.

The decision to what material to use for a specific pattern depend on:

1. Expecting production quantity.

2. Dimensional accuracy require?.

3. Molding process to be used in the foundry, including type and size of molding machine if one is used.

4, Size and shape of casting.

Appendix 10 presents a cortiparison of the important characteristic of four commonly used pattern materials - wood, aluminum, steel and plastic.

(The pattern for our project will be made of aluminum.)

Metal pattems are normally rnade from an aluminum alloy, gray iron, steel ora magnesium or copper alloy. The property on which metal selection is based includes resistance to wear, dimension stability machine ability and the ability to provide a smooth surface finish after machining. After metal patterns are cast, gating and flash must be removed, and the surfaces must be made smooth and free of imperfections.

Metal patterns afford better dimensional tolerances than wood patterns, longer pattern life, grater resistance to abrasion in molding, and for greater stability under changing humidity.

2.2.1 Type of patterns

The type of pattern used in a specific production application is determined by the number of castings required, the stage of development of the design of the casting the complexity of the design of the casting, and the molding process used in the foundry.

2.3 Selection of pattern type

The number of casting to be produced and the accuracy required are pritnary consideration of the choice of an appropriate type of pattern. Patterns, which are that de of metal, will retain accuracy longer. The number of casting to be produced also determines the molding equipment that will be used and the equipment available also affects pattern choice. After the design and quality of the casting have been approved, a permanent pattern is

selected, based on annual production requirements.

Seeappendix 11,12,13,and 14.

2.4 Allowance

The modifications that are incorporated into a pattern are called allowances, and the most important of these is the shrinkage allowance. Following the solidification, the casting continues to contract as it cools, the amount of contraction being as much as 2%. Thus the pattern must be made slightly larger than the desired casting as a mean of compensation. The exact allowance depends on the metal that is to be cast. Allowances typical of some engineering metals are:

Cast iron	0.8%-1.0%
Steel	1.5%-2.0%
Aluminum	1.0%-1.3%
Magnesium	1.0%":.13%
Brass	1.5%

The wood pattern is made 5% greater than the part to be cast, in order to let the shrinkage of the aluminum'pattern and the machining after the casting of the pattern then we can use this pattern for casting:

2.5 Conclusion

Choosing the pattern type and material is the most important part of the casting since it determines whether casting may be good or not. And also the cost of the casting products can be less by the proper selection of the pattern type and material.

CH.3 THE CASTING PROCESS

3.1 Introduction

Sand casting represents one of the wellknown and famous casting because of it is relatively cheap method of casting and furthermore because of its relatively good quality.

3.2 Sand molding

Sand combined with a suitable binder, can be packed rigidity about a pattern, so that when the pattern is removed, a cavity correspondence to the shape of the pattern remains. Molten metal poured into this cavity and solidified develops a cast replica of the pattern.

The sand that forms is friable after the metal is cast, and can be readily be broken away for removal of the casting.

The ingredients that the sand (silica 90%) is mixes with: Clay (3%), and water(7%).

,3.2.1 T)'peş of molds

Molds for sand casting are broadly classified as:

- (a) Green sand molds
- (b) Skin-dived molds
- (c) Dry sand molds
- (d) Dry sand core-molds
- (e) Other types of sand molds.

Green sand molds are the most widely used of all sand molds. They are made of sand, clay, water, and other conditioning. Both ferrous and non-ferrous castings are produced in these molds. The molds are prepared, metal is poured, and castings are shaken out in rapid production cycles.

3.2.3 Advantages of green sand molds

- 1. Green sand molding is the least expensive method of producing a mold.
- 2. There is less distortion than in dry sand molds, because no braking is required.
- 3. Flasks are ready for reuse in minimum time.
- 4. Dimensional accuracy is good across the parting line.
- / 5. There is less danger of hot tearing of casting than in other types of molds.

3.2.4 Disadvantages of green sand molds

- 1. Sand control is more critical than in dry sand mold.
- 2. Erosion in the mold is more common in the production of large castings.
- 3. Surface finish deteriorates s the weight of the casting increases.

3.2.5 Conditioning of molding sands.

Conditioning of molding sands may consist of one or more steps, includingSiriple mixing of the sand with other ingredients, mulling of the ingredients, coôling öf the sand from shakeout, and removal of the foreign material from the sand. See a:ppehdix 21 and 22.

3.2.5.1 The importance of sand treating

Refractoriness: the ability to withstand high temperature (basic nature of sand). Cohesiveness: the ability to retain a given shape when packed into a mold. Permeability: the ability to permit gases to escape. Collapsibility: the ability to permit the metal to shrink after it solidifies and to ultimately

free the casting through disintegration of the mold.

3.2.6 Allowance for metal shrmkage

In mold construction it is necessary to compensate for the following, to obtain accurate casting dimensions:

- 1. Mold-wall movement caused by thermal effect and static pressure of the molten metals.
- 2. Solidification shrinkage. This is i'metal feeding problem.
- 3. Thermal contraction of solidified castings. (See appendix 21 for shrinkage.)

Gray cast iron 1/10

3.2.7 Risers

A riser is a reservoir of molten attached to the casting, to provide it with metal required because of shrinkage before and after solidification.

The metal poured into the casting cavity should begin to solidify at an extreme distance from the risers. Freezing should then advance toward the metal feeding elements iri such a manner that the solidification shrinkage is progressively fooved frôi the body of the casting and is contained entirely in the feeding system.

During the solidification of a casting , a thin.skin offrozer1ineta.ls forms like a shell is ,in effect, a mold for the remainder of the casting, and the v6lt111le lost by the shrinkage of the 111tm.ar~ as it solidifies within this shell must be replaced , from some feeding source, to avoid shrinkage porosity.

The function of a pad or a riser is to supply liquid metal to the mass continuously until it is frozen solid without porosity. The thickened section provides feed path not to freeze until the isolated section.has solidifies.

See appendixl 8 for the riser design.

3.3 Cleaning the castings

The cleaning of castings usually refers to the operntions pvoly in th~ removal of sand and scale, gates and risers, and fines, chaplets or other metal not a pair of the casting.

3.3.1 Removal of gates and risers:

Usually is the first operation of cleaning. The gating system may be brokenµy.impact as the casting are dumped out of the flasks and vibrated and taken off. Those gates and riser not broken during the shakeout cari be removed by being struck with a hammer. When the molds are set on the cleaning floor and dumped by hand, the gating systemcan knocked off with a hammer. When the gating system can not be safely removed by impact, shearing can cut it off

3.4 Sand cores and core making

Cores are separate shapes of sand that are placed in the mold to provide castings with contours, cavities and passages that are not otherwise practically or physically obtained by the mold. Cores are composed mainly of sand but also worthat one or more binder materials most of the principles that are applied for making a sand mold are applied for making a sand core. After the core box being make, sand is pressurized .into the core to get the required shape, after that the box is opened and the core is taken to the oven in order to dry and get the final strong shape, Appendix 15 represents the core box.

3.4.1 Core requirement:

During its preparation, a core must be hard enough to retain its shape without deforming. After baking or drying, it must be strong enough to withstand handling and to resist erosion ind deformation by metal during the filling of the mold. To make a true form for the casting, it must be stable with a minimum of contraction and expansion. The core must be sufficiently low in residual gas-forming material to prevent excess gas from entering the metal.

Provision must be made for venting any gases that are produced by the core.

Furthermore, the core must collapse after the molten metal solidifies, to minimize strains from the casting during shakeout.

3.4.2 Core boxes.

The most common method of forming cores is to use a core box, made of metal or wood, that contains a cavity the shape o:rtfie desired core.

This cavity is rammed full of sand to form the core, which is mounted on a support plate for backing.

3.4.3 Core mixture,

The composition of the mixtures depends on the metal being cast and the strength.required for the core.

3.4.3 **OII** sand.

Oil sand mixtures are those most widely used for cores in sand molds.

Their cost is low and by varying their composition they can be used for alrrost any sand application. The following is a typical formulation that contains cereal and **a** small amount of clay; this mixture has proved satisfactory for the casting of gra.yiron and several other metals.

Sand (by weight)	95.8%
Cereal flour	1.01%
Core oil.	1.1 7%
Water•.	1.86%
Betonite	0.16%

These materials are mixed in a Muller as follows:

- 1. Combined sand, flour and betonite, and mull dry for 1 min.
- 2. .Add water and mull for 1 min.
- 3; Add oil and mull for 4 min.

See appendix 15 for the COre box.

The core is placed in the fnold cavity by tidying it to the mold by the mean of a thin wire in order not to fall down du, ting pouring the metal.

3.5 Preparing the molds.

3.5.1 For the cover

After the send is being prepared the following steps are followed:

- 1. The pattern is maintained in the drag part of the flask (the bottom of the flask should be covered with a thin wood plate).
- 2. We' add the sand to the flask everywhere and pack it well until it totally covers the pattern of the half part of the flask, then the sand should be packed well by squeezing it using squeezing equipment)
- 3. The flask is turned over, the wood part is taken away and cope is placed over the drag.
- 4. The riser and the sprue are hold in the flask and then sand is added until the cope is totally filled with sand, then the sand is squeezed well and after that some small holes are made in the sand with the aid of a 4 or 5mm in diameter nail in order to let the gases and theairhold in the hollow to escape,

- 5, The flask is then opened.(cope and drag are seperated)
- 6. The pattern, riser and the sprue are take away.
- 7. Then the two green sand cores are maintained in their places in order to be able to produce the two keyholes existing in the pattern.
- 8. A runner is opened between the sprue, riser and the hollow of the pattern.
- 9. The flask is locked again before getting ready for casting.

3.5.2 For the chamber

After the sand is being prepared the following steps are followed:

- 1. The pattern is maintained in the drag part of the flask.
- 2. The sheet metal is inserted in the hollow of the chamber after being locked.
- "3. The sand i~ added orily in the part between the exterior circumference of the sheet metal and the interior part of the flux, then the sand should be squeezed well by squeezing machine.
- 4. The flask is turned over and the wood part is taken away and the cope is placed on the drag.
- 5. The riser and the sprue are hold in the flask and then sand is added üntil the flask is totally filled with sand, then the sand is squeezed well and after that some small holes are made in the sand with the aid of a 4 or Sinin in diameter nail ihördeftoletthe gases and the air hold in the hollow to escape.
- 6. The two parts of the mold are separated.
- 7. The sprue and the riser are taken away then the sheet metal is unlocked and removed so that the pattern could be removed.
- 8. The mold is packed again and ready for casting:

See appendix 19.

3.6 Casting process

In the early morning the scraps and the coke are inserted in the charging door and let them to melt; after being melt, the molten metals are poured into a shank-type ladle (see appendixl 7) that is hold and then taken away by the mean of a crane to the molds area where an experienced labor should pour the molten metals into the mold.

3.6.1 The points that the responsible worker of the poufing should take care of:

The flow rate of the niolten metals.

He should stop when he sees the riser full of molten metal withoutforgettingto keep an eye on the sprues.

Note: 90% scraps of cast iron and 10% scraps of steel.

3.6.2 Flasks:

The flasks should be squared iron boxes that are opened at the top and bottôrii.iii order to let the feeding of the sand .the figure shows the shape and the dimensions of the flasks. ^a See appendix20..

3.7 summary

In order to have a good quantity production, the experience is need.eclinthis field since most of the steps being stated are not theoretical, so one should not expect to have good production at the beginning without having experience.

CH 4 MELTING CAST IRON

4.1 Introductiôn

X

One of the most iripôrtant steps in casting is to determine the type of the furnace and the temperature of the in,ôltenmetals, If the temperature of the molten metal was not higher enough, there will be hiprôper solidification appears in the body of the casting which leads to a had product or eveti a wrong one.

On the other hand, had results will appear on the product if the molten Berature was liigher than necessary.

The manufactures use Cupolas for melting the cast iron.

4.2 Cupolas

The primary function of a cupola is to melt iron to a specified tapping temperature and chemical composition using as little coke as possible. A cupola is a """.ttical steel shaft into which coke, flux andmetal are in alternating layers.

Cupolas (such as those shown in appendixl) are prepared for *mysetthetion* of by closing the bottom door, supporting them by a prop, then placing at them a bed of rammed sand 6 to 10 in. thick.

The taphole for iron is at the edge of the sand surface, the rows of tuyeres for entry for air is 12 to 36 in. above the sand, depending on the cupola size and whether tapping is intermittent or continuous. A bed of coke is placed on the sand bottom and ignited, and then made up to a height of $50 \cdot to 60$ in. above the tuyeres. The shaft is filled through the charging door with alternate layers of coke and metallic charge.

Air supply or blast is then introduced through tuyeres and intense heat of combustion is thereby develops in the bed coke. The metal at the surface of the, bed melts and trickles down through the hot coke to collect on the sand bottom in the well bellow the tuyeres. The column of the charge materials descends to replace the metals melted, and afreshJayer of coke replenishes the coke burned in the bed to melt one charge. This process continues as long as air supply is continued and coke and metallic charges are added. Molten slag which is coke aslı and nonmetallic in the charges is also formed and floats on the surface of the molten iron in the well.

If the cupola is continuously tapped, as most medium size and large cupolas are, the iron 'and the slag flows continuously through the same tapehole and are separated in a small basin in the spout, the slag floating and being discarded. For intermittent tapping, there is bothari iron tapehole in the front of the cupola and a slag taphole at the rear some 12 to 24 in. higher.

'Ilie iron taphole is closed with a fierclay plug, so that iron and slag are accumulated in the well, as the level rises, the molten slag floating on the iron reaches the slag hole and flows out. When the iron level is near or at that slag hole the iron tapehole is opened by removing the fierclay plug and most of the iron is drained out at rate much higher than the melting rate.

Then the iron tapehole is .redosed and the cycle is repeated.

Çonventional cupolas have refractory linings from the sand bottom up to thecharging door, At the top gray iron blocks are used for lining because they are less susceptible to damage from the charge materials then are refractory linings and the temperature here is not high. The stack portion of the cupola is lined with refractory but because temperatures are relatively low in the stack the type of refractory used is less critical.

Size of cupola may vary from one that melts no more than one ton per.hourto.one that melts nearly 50 tons per hour. Cupolas are usually rated in capacity by their inside diameter, it is possible to operate a specific cupola within amoderate ange of melting rates by varying the air blast and the percentage of coke in the charge. (See appendix 2 for the size of cupola).

4.2.1 Air blast.

The forced air required for combustion of coke in the cupola can be supplied by positive - displacement, centrifugal, or fan blower. The .pressure required depends on the type of charge, height of the charging door above the.tuyeres, and air volume blown, but usually it is about 1 oz per sq. in per foot charge height. A 32-0z blower is ordinary sufficient. It is important to measure and control air volume or weight since approximately one ton of air is consumed in melting one ton of iron. if the blast is 'to be heated, as in a hglr-blast cupola the air is passed through a gas fired or oil fired heatel"ifu.meôiafely before entering into the cupola.

The air for combustion is supplied to a wind box that encircles 1:he cupôla. From the wind box, the air is admitted to the cupola through tuyeres, positioned tunifotinly about the circumference of the cupola. Tuyeres are usually located on one leV~l, irtd hioÔei:ri pfactice _is to use relatively small tuyeres to give an air velocity 50 feet per second at normal \temperature and pressure for good penetration, except in vefy smallC\l.polas.

Combustion of the cupola takes place in the coke bed. The zône.ôfrri.aximutn temperature extends from about 5 to 20 in above tuyellevel, and it coincides with the zone of maximum refractory erosion in a lined cupola. Melting of charge material takes place at a somewhat higher level, depending on the melting point of the particular ifon, and it is in this bed of hot coke that melted iron a truckling down picks up its super heat.

If coke is added in the charge in less proportion than required tharithea.irstipplythe top of the bed is not replenished fully and it slowly burns to a lower level. This shörtehs the super - heating zone, and the iron becomes colder at the taphole. Conversely, excess coke makes too hot iron so s balance must be struck for uniform operation. In principle there are fixed relations among melting rate, iron temperature, percentage of coke charge u.üd air blast rate, 61,"~ V., M., I_ and varies charts J.; as been published to simplify prediction. However, Jhe .relations also depend on coke quality, on the air distributi on' in a given cupola, and ön height from tuyers to top of charge column, so they become rules of thumb. The simplest rule is that a cupola normally will burn coke at a fairly constant rate of 1.1 to 1.2 lb. of coke per square inch of cross-section per hour, taking about 110 cu ft of air per pound 91% fixed carbon coke.

4.2.3 Slag disposal.

The slag formed in the cupola is removed continuously; if the volume of the slag is small, it may be run dut on a dry sand bed and carried out with the bottom drop. Large volumes of slag are into suitable slag pots and cooled, and then taken to a slag dump after the metal buttons that from at the bottom of the pots are removed.

4.2.4 Disposal of the cupola drops.

When the required amount of iron is melted in jobbingshop,. or illternal repair becomes necessary in a continuously operated cupola, the cupola must be emptied. This is accomplished by dropping the bottomf doors after all molten füet.a.iallq slag have been tapped from the cupola.

The remaining material, which makes up the drop, is a mixture of sand coke, iron'and slag. The drop may be cooled in a place by water hose and removed or preferably (to permit the cupola to cool and to make a the work easier), the drop is pulled from under the cupola and cooled; then the drop is sorted; some unburned coke and partly melted iron are recoverable *r* and the remainder is discarded.

4.2.5 Metal Tapping.

Metal is usually tapped from the cupola to transfer ladle or to tilting forehearth, called a mixing ladle, either of which is located in front of the cupola. Both of these containers must be heated before receiving the molten metal, in order to maintain iron temperature. The forhearth may have an auxiliary system for continuos heating.

4.2.6 Advantages of Cupola Melting.

They include flexibility in using a variety of low-cost materials to produce ğray iron, high melting rates, low fixed cost per unit of output, continuos (for a week.or more), and minimum down time.

4.2.7 Cupola l,İıtingsA cupola is divided irito four zones:

1. The well or hearth;

2. The melting zone (the area immediately above the tuyeres, which varies in height depending on the initial height f the coke bed, the blast velocity and the degree of blast penetration);

3. The preheating zone

4

4. The stag above the charging door.

Temperatures and other conditions vary considerably among these four zones; thus, the requirements for refractory linings also vary.

Temperatures in the cupola well are several hundred degrees lower than in the melting zone. However refractors in the well are exposed to molten iron and slag and must resist attack from these materials.

Maximum attack on the refractory lining occurs in the melting zone, where maximum temperature is generated (usually, about 3250 F). The high temperature accelerates the erosion oxidation of the lining materials by the hot gases, slag, flux, and iron oxide.

Temperature of the preheated zone decreases rapidly from the melting zone upward, as the result of absorption of heat by the descending charge, and linings are not in contact with molten iron and slag. However, linings in the preheating zone are subjected to sever abrasion from the dovvnward movetnent of the materials of the charge and the impact of the charge as it is duti:iped iritö the cupola.

in the cupola stack above .the charging doôr, côiiditiôris are 'not sever;>hei-e)thelining is required to withstand only the temperature of gases.

4.2.8 Refractory Iinings

They are built up inside the cupola shell to form a uniform circular shape of predetermined size and thickness.

The original lining is installed most economically by using fire clay refractors manufactured in standard shapes.

Cupola blocks or shapes can be used for construction of the entire lining. The stack above the charging door is normally limned with brick that is bounded with a mortar of air setting high temperature cement. Because service requirements in this area are not severe, the brickwork usually lasts for a long time with little or no maintenance. Cast iron blocks are often installed at the area near the charging door where abrasion from impact of charge materials can cause rapid failure of refractory material.

The melting zone, where most refractory is consumed, is lined with brick ramming mix or, to minor extent silica stone slabs.

4.2.8.1 Thiclmess of lining.

Depends on the size of the cupola, the location of the cupola, and the length of the usual operating period. Typical lining thickness for cupolas of various sizes are given in appendix4

In a refractory-lined cupola, the maximum consumption of refractory is in the melting zone, and erosion to a depth of 8 in. in a band 12 to 15 in. high is common. Most of this erosion occurs in the first one to three hrs of operation, and the rate then decreases as the thinner lining is cooled by convection from the shell. Abnormally high consumption of lining material may be caused by excessive blast volume, excessive fluxing , a high proportion of steel serap in the charge , the use of an undersize cupola, or an uneven charging practice.

4.2.9 Cupola Bottofü

Cupolas have hinged metal doors at the bottoms that are dropped at the end of each heat or when repair is required. This type of bottoms requires a layer of refractory that is strong enough to support the molten metal, but is still weak enough to fall out when the bottom doors are opened. Foundry sand mixed with a little fireclay or bentonite and water is the most commonly used refractory.

Bottom doors must be prov. ided with vent holes μ_4 to $\frac{1}{12}$ in μ_4 to $\frac{1}{12}$ in μ_4 to provide and to provide and to escape. If vents are not provided and kept opened entrapped steam is likely to blow up section of the sand 'bottom, causing run outs of molten iron.

Before the bottom doors are closed, the joints are daubed with refractory materials to ensure a good fit. Often arrow of firebrick is placed around the edges, especially in large cupolas.

The doors are held in place by props that are wedged upward from a firm foundation. The number of props used depends on the size of cupola, but it is good practice to make certain that the bottom is firefly propped, because a premature drop can be disastrous.

For cupolas that are to be operated for a few hours each day and the bottom then dropped for repair, the sand for the bottom is not critical; screened modeling sand, well ramped to a depth 4 to 6 in., is sufficient.

The sand is dumped into the cupola through the charging door and spread evenly over the bottom. It is then rammed with the peen end of the rammer into a large fillet against the lining of the wall. Two or three ramming are generally used.

The level of the bottom is slanted towards the taphole with a slope of about 1-in. per foot.(see appendix3).

4.2.10 Cupola Charges.

A cupola charge id composed of metal, fuel (coke), in the flux. Because of the changes in composition that take place during melting, the makeup of the charge is based largely on experience.

4.2.11 Cupola Operatfo~

Cupolas may be designed for eitherititermittetitor continuos tapping.

4.2.12 Intermittent 1'apping.

For intermittent tapping the operator manually removes the disposal sand Or day plug from the cupola taphole, with draws the needed amount of molten iron arid then plugs the taphole. This process is repeated with the rate of withdrawal and' inelting rate per hour being balanced. The maximum amount that can be tapped at one time is determined by the diameter of the cupola and the height of the tuyeres above the bottorn sand. Intermittent Itapping requires a skilled cupola operator.

Intermittent tapping is generally restricted to jobbing foundries where the demand for iron is intermittent and small and where conventional cupolas are used. For such operation a

relatively large tap is necessary to prevent freeze-ups, because the tapholes and slagholes must be heated by the metal in the well. For intermittent tapping, as regular a pattern as possible should be possible, since iron held in the well picks up carbon from the cock. This must also be correlated with slag withdrawal at the rate of the cupola, so the reasonably consist slag layer is maintained an intermittently tap cupola may be used with of without forhealth.

Any cupola can be operated in a flexible manner but the degree of control of result increase and costs decrease, as uniformity of operation increases.

A small cupola for melting 5 to 50 tons of iron per day may be simple and inexpensive. A cupola of this type usually has acid linings, uses cold blasts, is quipped for manual of mechanical charging, and as minimum control measure has aif~weightcöritrol.The size of the heat is limited only by the deterioration of the refractory lining. Two ör three classes of iron are commonly pröduced during one heat.. The operation of a srna.Uicupola is sufficiently simple that öperators can become efficient after a moderate training period.control of the operation, however, is limited. The metal temperature of the pouring spout, which is a critical variable, is controlled by the initial and continuing bed height, the size of the coke, and the blast volume. These variables must be carefully adjusted and,. controlled for maintenance of proper metal temperature, (See appendix 5).

4.2.13 Cupola Temperature

3

The temperature in the cupola stack is lowest at the top and ta.pidlY iricreaseSdôwt1 the stack, becoming highest just above the level of the tyueres. Below. the tytieres the temperature drops gradually, but remains above the melting points of the slag and iron. The temperature in the cupola stack and the shape of the zone of maximum temperature depend on several variables including blast temperature and tuyre Iocation .•For cold blast operation, the lowest part of the zone of maximum temperature in the cupola is about 5 in above the tuyere level (appendix 6a). As also seen in appendix 6 a, the height temperature zone is relatively narrow but extends upward to approximately 23 in above the tuyeres. When a hot blast is used (appendix 6b), the high temperature zone is not only lower and slightly shorter but also broader. The major causes of variations in iron temperature are variation in air blast volume, coke bed height and metal to coke ratio.

4.2.13.1 Hot Blast in the Cup ola

Hot blast applied to the cupola increases iron temperature, decreasescoke consumption per ton of iron melted, increases melting tate, and provides secondary benefits iri'the form of lower melting losses, less sulfur pick up, and increased ability to use lower carbon low material. The importance of hot blast are shown in the appendices 7, 8 and 9.

4.2.13.2 Iron 'I'emperature.

When the temperature of the air supplied to a cupola is increased, with no change in the amount of coke as a percentage of charge weight, the temperature of the iron at the spout increases. The increase in iron temperature is proportional to the increase in air temperature, approximately 15 F for every 100 F increase in air temperature as shown in appendix 7.

4.2.14 Coke required,

The use of hot blasted, by increasing iron temperature, makes possible a decrease of the " amount of coke charğed to the cupola. Fora given tapping temperature, each 100F increase in air temperatute rriakes pôssfble a decrease of 0.4 % of chatged weight in the amount of coke used (appendix 8). So ifwe take the point where the air temperature is about 100 F, a 2251bof coke are required per ton of iron.

4.2.15 Melting rate

Operating results of a large number of cupolas have shown that the melting rate is linearly related to the coke rate (percentage of coke in the charge) over wide ranges of operating - conditions and types of coke.

If the buming rate of the coke in 1b per hour is constant, and if the amount of coke 'necessary to melt the iron is decreased by hot blast, melting rate in tons per hr increases in proportion to the blast air temperature. With no change in the air temperature, a decrease in the tapping temperature would result from a decrease of the coke rate; but with a suitable increase in air temperature, the decrease in iron temperature can be eliminated, yielding an increase melting rate with no decrease in tapping temperature. Thus, the use of hot blast will increase the melting rate of a cupola at given iron tapping temperature (appendix 9). Air volume must be maintained, since the coke-buming rate is unchanged. If the increase iron flow cannot be used, air volume must be decrease and the cupola must be operated bellow its normal capacity.

4.2.16 Air supply.

Ï

When the amount of coke necessary to melt a ton of iron is decreased by the use of hot blast, there is a corresponding decrease in the amount of combustion air necessary per ton of iron. this means that if hot blast is applied to a coke cupola without increasing the melting rate, the melting of the sir heater(in a cubic feet per min.) will be less than the requirement of the same cupola when it is operated in the same blast.

There is a small decrease in the amount of air necessary per pound of coke burned with the hot blast, and a small decrease in carbon dioxide content of top gases, but neither with these effects is large enough to be of engineering importance.

4.3 Summary

As seen, the temperature is very important in the cupola and also the atnount of the used coke. Since every thing is a matter of money, it is better to reduce the amount of the use of coke but at the same time we should use the suitable pressure in the air blast.

CH 5 COST ANALYSIS

5.1 Introduction

X

In most of the application of working places in the world, finance is the most important factor since it determines the production ability.

So a factory must determine the least cost with respect to the customers needs.

5.2 Cost analysis.

5.2.1 the production requested elements

Each unit of covering needs should weight 200 kg (120 kg for the chamber + 80 kg for the chamber). But when production we should take the weight of the looses into account; These looses are due to:

- 1. Weight of the solidified metal in the sprues, riser, runner and that of loses due to the machining if necessary.
- 2. The slag and the stuck metal in the cupola.
- 3. Other loses like some drops on the ground.

Due to these factors, more amount of the raw material should be used so that we can take a 15% more weight of the molten iron; so after easy calculation we can get the weight of the molten metal of one unit production to be 230 kg.

material	Price in \$/kg	Amount(kg)	Cost (\$)
Raw gray cast iron	1	25,000	25,000
scraps	0.3	437,000	131,100
Coke	0.'5	66,500	33,250
Limestone	0.0134	23,500	3,149
sand	0.3	5,000	1,500

Other costs:

t Amurak i

3

Labors: 6% \$500 %12 months = \$36,000

Others: alcohol, graphite ete.

Cost = \$230,164

The cost per piece = \$230164/2000=\$115.082

5.2.2 Percentage amount of the part

5.2.3 The cost of one unit

5.3 Summary

和可非

S)

Everything that affect the cost of the production should be taken into account especially if one wants to have the best quality that could be afforded in the cheapest price that could be cost because the life is a matter of safety and savirig money.



Fig. 2. Sectional views of connentfonal and water-cooled cunolas

|--|

..

Appendix 2: size of cupolas

\$ \$}}}, },



1

ģ

'n



Appendix 4: typical thickness of cupola lining



Appendix 5: advantages and disadVantages of tUpÔla melting in a small foundry

I.

T11.ble 11. Atlvanlu.ges nnd l)isMlv11.nluges of cu1,ola M.elUng in a sm11.11 FoundrY

- 1 r,Aoder11.tecl\pl.to.1 co1;ts 11.nd 10w nxed costs
- 5 Flexibility of size of bout composition during ilent
- 4 Hlgh meit.ing rii.tes

5

- 6 0 1/8
- Modern.te relf.MtorY costs Modern.te relf.MtorY costs Modern.te genern.ima\ntenn.ince Reln.tlvelY simple cupolii. opern.tlon. Dlsin.dvantages
- 1' |_____3
- L\in\ted control of tempero.ture Limited control ol metiil compos\tion Metiil chiirges iire costlY becii.use ol prepa-
 - 4 cim.rge requires extensive prepu.ru.tlon u.nd
 - weigh settur pickup dudng meiting Metal ii.nd n.lloy losses are reln.fively b\g\l. 8

Appendix 6: temperature distribution in the cupola



FlfIr6. Lacations and sha1)CS of than the second share of the second strain to the second sec

•••_



\$



Appendix 8: effect of blast air temperature on melting rate









Ś

and a second	- 01	aracte	ristics	1a
Table 1. Compariso Pattern	n of Of Mater	als : Fair;	P: Po	or)
(E: Excellent; G: C	Wood Al	ittern me uminum	steel P	lastlo
Characteristic	E	G	F	F
Machinability Wear resistance	P F E	Ğ	E P C	G F
Strength Weight (a) Repairability	E	Р Е	P	E E
Resistance Corrosion(b)	P	E W. P.	winter,	"Intro- raw-Hill
BOURCE: D. C. E BOURCE: D. C. E duction to Found New Y	key and dry Tec ork, 195	nnology 3, p 46	ue, (b)	By water.
(a) As a factor if	oper u	0		

п



\$







----,

ne ne ang

fi



٠,

\$

<.





43



Ś

44



)]

₹ ≻







CORE Box



'...'" :,.....'!



..•..

Appendix 16: the foundry outlook view

A 12×30 m foundary

".

Appendix 17: the shank type ladle



ţ

1

Appendix 18: the riser design

Dr riser diameter

Vr: volume of the riser

Ar: Area of the riser

Vc: volume of the cover casting part

Veh: Volume of the chamber casting part

Ach: Area of the chamber casting part

(TST)r: Total solidification time for riser

(T2ST)ch: Total solidification time for chamber casting part

(TST)c: Total solidification time for cover casting part

Cm: mold constant

Using Chvorinov's rule: TST= Cm (V/A)₂

$$(T_{S}T)_{\text{casting}} < (T_{S}T)_{\text{Rise}} \Rightarrow \left[C_{m} \left(\frac{V}{H} \right)^{2} \right]_{\text{casting}} < \left[\left(\frac{V}{H} \right)^{2} \right]_{\text{Rise}} \\ \Rightarrow \left(\frac{V}{H} \right)_{\text{casting}} < \left(\frac{V}{H} \right)_{\text{rise}} \qquad \text{assume} \quad h = \frac{3}{5} D \\ V_{R} = \frac{T}{4} \frac{D^{2}}{4} \times h = \frac{T}{4} \frac{D^{2}}{5} \times \frac{3}{5} D = \frac{3}{5} \frac{T}{20} \frac{D^{3}}{20} \right] \Rightarrow \frac{V_{R}}{H_{R}} = \frac{11}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} \frac{D^{2}}{4} = \frac{11T_{0} D^{2}}{10} \int \frac{1}{20} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} \frac{D^{2}}{4} = \frac{11T_{0} D^{2}}{10} \int \frac{1}{20} \frac{3D}{4} = \frac{11}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} = \frac{11T_{0} D^{2}}{10} \int \frac{1}{20} \frac{1}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} + \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} + \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} + \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{3D}{30} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} + \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{1}{10} \frac{1}{10} \\ H_{R} = T_{0} D_{0} H + 2T_{0} D_{0}^{2} + \frac{1}{10} $

$$\int -\frac{IL}{y} = \frac{Mc}{P} = \frac{80,000 \text{ kg}}{7.5 \text{ s}/\text{cm}^3} = 10666.67 \text{ cm}^3$$

$$Nch = \frac{Mch}{P} = \frac{120,000 \text{ kg}}{7.5 \text{ s}/\text{cm}^3} = 16000 \text{ cm}^3$$
for the Cover

$$Ac = \pi.65 \times 620 + \frac{\pi}{4} \times \frac{(620)^2}{4} = 130820 \times \pi = 1.0 \text{ If Wt} = 1.0$$

j-0-1,. → h*t* c \1.~, 11,/,rt

Ac1,~ n ~ 6'Hin1.1 II Z .,- 'lr (
$$l',l'S_{-6}$$
 . JJJ['] + -~($(,J'5-t.1(,)^{1} + ~ (l.), ..., l8)^{n}$
1-ich::. ? s $l;$, 6 no^{-1} ,,,n',"
'JC. _ \oH6,JJ_>1'...':o ,,,,n',"
-U,. - -'li:10, 'fr1., ..., II
'J,...' - 'li:10, 'l

۰,

Appendix 19: the mold preparing steps

328 Casling Processes "

._..."....."...





1.1

١

220

LIBRAF



Pr-1RT -~~. E~.: T L A s K (JvqJ Ch,cl c .35 rieccs 52 Material: sheet metal 5mm thick





